

Direct Sourcing Solutions

New Products [Replacement Scania) May 2021



110178

2176067

Oil Mist Separator Repair Kit

PGRT Series - D9/D13

LPGRS Series - DC13/DC16 FKN Series

Bus - D9/D13




110191

1926895

Crankcase Cover Gasket

PGRT Series - D9/D9 XPI

FKN Series Bus - D9/D9 XPI



110196

1892899

Oil Pump Repair Kit

PGRT Series - D9/D11/D12/D13

FKN Series Bus - D9/D11/D12/D13



120113

2038638 1790071

Radiator Hose

PGRT Series - All engines



160077

1874642

ABS Sensor L/H Rear Axle

FKN Series Bus



160078

1874641

ABS Sensor R/H Rear Axle

FKN Series Bus



170091

300128

Air Bag R Clip

All vehicles



130261

1496308 478495

Throttle Pedal Position Sensor

4 Series Bus



190532

1915256

Bumper Bracket L/H

PGRT Series - Low Bumper



190533

1915257

Bumper Bracket R/H

PGRT Series - Low Bumper



Suffix Key; OE = Original Equipment, R = Reconditioned Part
OEM = Original Equipment Manufacturer, ALT = Alternative Supplier Part

OE Numbers used for Cross Reference Purposes Only

Direct Sourcing Solutions

New Products [Replacement Scania) May 2021



190522

1900181 1514498

Cab Mount Bracket Cap L/H

PGRT Series

for 190173



190523

1900182 1514499

Cab Mount Bracket Cap R/H

PGRT Series

for 190174



Suffix Key; OE = Original Equipment, R = Reconditioned Part

OEM = Original Equipment Manufacturer, ALT = Alternative Supplier Part

OE Numbers used for Cross Reference Purposes Only